


Attachment 4

Updated Photo Survey – May
2022



Photograph Location and Direction





A. Photograph looking northeast from northeastern corner of the project site.



B. Photograph looking west from northeastern corner of the project site.

Site Photographs



A. Photograph looking south from northeastern corner of the project site.



B. Photograph looking north from northeastern corner of the project site.

Site Photographs



A. Photograph looking south from northwestern corner of the project site.



B. Photograph looking east from northwestern corner of the project site.

Site Photographs



A. Photograph looking north from northwestern corner of the project site.



B. Photograph looking west from northwestern corner of the project site.

Site Photographs



A. Photograph looking east from the center of the project site.



B. Photograph looking north from the center of the project site.



C. Photograph looking west from the center of the project site.



D. Photograph looking south from the center of the project site.

Site Photographs



A. Photograph looking south from the center of the project site.



B. Photograph looking west from the center of the project site.

Site Photographs



A. Photograph looking south from Country Club Drive near northwestern corner of the project site.



B. Photograph looking northeast from Country Club Drive near the southwestern corner at Hill Valley Drive.

Site Photographs